



SERVICE BULLETIN			
DATE	26/02/2020	BULLETIN	F39-1
MODELS	ALL HINO MODELS	PAGE	1 of 3
SUBJECT	HINO PARK SERVICE INTERVALS		

From the 27th Feb 2020 there is a NZTA requirement to service the **Park Brake lever Assy** as per the manufacture’s requirements. In addition there is a requirement to complete a form known as the 4085D found on the NZTA site. If the Truck is over the age of two years the Vehicle inspector may request this form to be completed and provided at the vehicle COF.

Please find below the **Hino Manufactures Recommended Service Intervals** for servicing the Park Brake Lever. This includes both cable & air type parking systems on all Hino 300, 500 & 700 Series Models

https://vehicleinspection.nzta.govt.nz/_data/assets/pdf_file/0006/74454/4085D-Operator-SoC-with-maintenance-requirements-for-park-brake-assemblies.pdf

HINO 300 SERIES

XZU & DUTRO XZU (UTILISING CABLE TYPE PARKING BRAKE (CARDON SHAFT))

- AS PER OWNERS MANUAL CHECK AND ADJUST AS NECESSARY THE PARKING BRAKE LEVER, CABLE & DRUM / SHOES ASSY EVERY 6MONTHS

HINO 500 SERIES INCLUDES FC, FD, FE, GD, GT, FG, GH, FM

- AS PER OWNERS MANUAL CHECK AND ADJUST AS NECESSARY EVERY 12 MONTHS, ALL RUBBER PERTS TO BE REPLACED EVERY 24 MONTHS

HINO 700 SERIES INCLUDES SH, FS, FY (ALSO INCLUDES FS1K & FY1E)

- AS PER OWNERS MANUAL CHECK AND ADJUST AS NECESSARY EVERY 12 MONTHS, ALL RUBBER PERTS TO BE REPLACED EVERY 24 MONTHS



HINO DISTRIBUTORS (NZ) LTD

Private Bag 11027
29 Malden Street
Palmerston North 4442

0800 367 446

info@hino.co.nz

www.hino.co.nz

It is highly recommended that all inspections and adjustments be carried out at local Truckstops Branch's or authorised Hino service agents

Hino Distributors NZ Ltd Technical Support
Division on 0800 367 446 (option 3).